

Release Notes EN RTW TouchControl 5 Firmware 1.0.4

Software version: rtw-tm5-fw_1.0.4.update

Build date: March 6th, 2025



ATTENTION! – If you want to power the unit off, please make sure that it is fully running before disconnecting power.

Release Notes Firmware 1.0.4

In a Nutshell - a service release

- | | |
|-------------------------|---|
| TM5 Ravenna | <ul style="list-style-type: none">• There was an issue when having more than one TouchMonitor 5 on the Ravenna network. Fixed. |
| Loudness | <ul style="list-style-type: none">• Trigger settings: TouchMonitor 5 is able to automatically start and stop loudness measurements, based on the trigger settings. There was an issue with this feature. Fixed. |
| Over Reset | <ul style="list-style-type: none">• Over Reset does not work as expected. Fixed. |
| Device | <ul style="list-style-type: none">• The Save button does not work as expected. Fixed. |
| WepApp - Routing | <ul style="list-style-type: none">• The Output option on the Routing page has been removed as the TouchMonitor 5 has no outputs. |

Important Notice

Trademark All products and company names contained herein are ™ and ® of their respective holders.

Copyright RTW GmbH & Co.KG
Am Wassermann 25 | 50829 Cologne | Germany

Support Visit www.rtw.com for support information